


# AMCO

## *Drilling Press*

*Model No: D100*

*Serial No: 103930*

*Operation Manual*



**WESTWAY Machinery Ltd.**  
"Exclusive Canadian Import Agent"

2370 Cawthra Road, Mississauga, ON L5A 2X1

Tel: (905) 803-9999 Fax: (905) 803-9109

Toll Free 1-800-263-1199

Website: [westwaymachinery.com](http://westwaymachinery.com)

Z5025A

Z5025 -1A  
-3A

UPRIGHT DRILLING MACHINE

# OPERATION MANUAL

MAX.DRILLING DIAMETER

25mm (1 in)

## CONTENTS

1. Outline Drawing
2. Main Applications and Features
3. Main Technical Specifications And Data
4. Transmission System
5. Main Structure
6. Electrics
7. Lubrication
8. Lifting and Installation
9. Operation Test Run and Adjustment
10. Accessories
11. Part list

\* This document is a general—purpose instruction, some differences between figures and objects are permitted.

1. Outline Drawing




Figure 1

## 2. Main Applications and Features

This machine tool is a kind of universal machine tool which is mainly applicable for drilling as well as for hold slash, spot facing, chamfering, reaming, tapping, boring, etc. maximum drilling diameter is 25mm. It is suitable for single-piece, small batch or large scale production and it is applicable to use in machine shop, fitting shop, repair shop.

Speed of main spindle is controlled by speed changing handle 5 and 6 <as show in figure 10 >. four <4> different speeds can be changed, with switch 14, spindle can obtai eight <8> different rotating speeds. After loosening clamping handle 9, spindle box can be moved up and down by handwheel 4 and can be rotated 360° around the vertical column Main spindle is in sleeve between ball bearing and roller bearing. The clearance of the spindle can be adjusted. Re-setting is controlled automatically by spring.

Only manual feed is available.

Driving gears are engaged by steel gears and MC nylon gears.

It runs with sweet sound and low noise.

All shafts are made of superior steel, critical area has been hardened.

Working table 16 is mounted on the supporting block 17.

Supporting block 17 can be turned 360° around the vertical column, working table can be turned 360° on the supporting block, after the mode has been changed, it can be tilted  $\pm 50^\circ$  also.

Depth of drill is ensured by scale 7 fixed on the sleeve and setting nut 8. It is reliable and easy job can be done.

In order to easily change tools the automatic tool stripping device is mounted in the spindle for drill holder, taper shank and taper sleeve stripping.

All critical casting parts are made of high-strength cast iron which passed through ageing treatment.

3. Main technical specification and data

No	Technical specifications and data		unit
3.1	Maximum drilling diameter - (5b = 500 - 600Mpa)		<in> <mm>
3.2	Maximum travel of spindle die.		<in> <mm>
3.3	Taper hole spindle		Morse No.3
3.4	Distance between the centre of spindle and the surface of the vertical column		<in> <mm>
3.5	Maximum distance between the spindle nose and the surface of working table		<in> <mm>
3.6	Maximum distance between the spindle nose and the base surface		<in> <mm>
3.7	Maximum travel of the supporting block of working table		<in> <mm>
3.8	Maximum travel of spindle box		<in> <mm>
3.9	Dimensions of working table		<in> <mm>
3.10	Steps of spindle		8
3.11	speeds of spindle		r/min
3.12	Dimensions of the base surface		<in> <mm>
3.13	Double - speed 3 - phase motor		type
			power kw
			speed r/min
3.14	Overall dimensions <L * W * H>		<in> <mm>
3.15	Weight of machine		kg

4. Transmission System

<As show in Figure 2>

The spindle with eight <8> different speeds is driven by motor shaft I through gears 10-11 or 9-18 to intermediate shaft II, and gears 12-16 or 13-14 to shaft III <the shaft III is keyed to spindle> feeding downward is performed by gear 20 driving toothed rack 19. Reposition of spindle sleeve can be performed automatically by spiral power spring fixed on gear 20.

Headstock can be moved up and down through worm 7, worm-gear 6, gear 5 and toothed rack 8.


Supporting block of working table can be moved up and down through worm 4, wormgear 3, gear 2 and toothed rack 1.

Distribution of roller bearings is as show as in Figure 3.

Schedule of the parts of Transmission

Name	Gear Box				Spindle Box							
	Supporting Block of Table, Column, Base											
Parts in Figure 2	1	2	3	4	5	6	7	8	9	10	11	
No. of Tooth	Z5025A	72	15	28	1	15	28	1	34	42	16	68
	Z5025-1/2A	80	20		17	43						
Module	Z5025A	2.5	2.5	2	2	2.5	2	2	2.5	1.5	1.5	1.5
	Z5025-1/2A	2	2		2	2						
Spiral Angle and Direction			5°6'8"		4°23'55"		4°23'55"					
Precision Grade	9-GJ	9-FH	9-De	9-De	9-FH	9-De	9-De	9-FH	7-GJ	7-FH	7-GJ	
Material	45	45	45	45	45	45	45	45	Mc nylon	45	Mc nylon	
Parts in Figure 2	12	13	14	15	16	17	18	19	20			
No of tooth	16	34	33		51		42	29	16			
Module	2	2	2		2		1.5	2	2			
Spiral Angle and Direction												
Precision Grade	7-FH	7-FH	7-GJ		7-GJ		7-FH	8-GJ	8-GJ			
Material	45	Mc nylon	45	45	Mc nylon	45	45	45	45	45		

Figure 2 Drawing of Transmission System.








Figure 3 Location of Rolling Bearings

List of Bearings

Code	Name of Bearings	specification	Qty	Precision Grade	Remarks
80203	Single—row centripeta ball bearing	17×40×12	6		
80205	Single—row centripeta ball bearing	25×52×15	1		
3056203	Double—row angular contact ball bearing	17×40×17.5	4		
2007107	Single—row tapered roller bearing	35×62×17	1	D	
8102	Single—way thrust ball bearing	15×28×9	2		
8124	Single—way thrust ball bearing	120×155×25	2		Z5025A
8120	Single—way thrust ball bearing	100×135×25	2		Z5025-1A-3A

5. Main Structure

See Fig. 13-18.

## 6. Electrics

Figure 4 is diagrammatical layout. Figure 5 is installation diagram of electrics. Figure 6 is wiring diagram. Electric components are show in list of Electrics.

Three phase AC power with 50HZ, 380V, 50HZ, 400V, 50HZ, 420V, and 60HZ, 220V are available to choose.

There is no fuse in the machine. We recommend that a three-phase 6A fuse should be placed in socket power. The ground wire must be grounded tightly.

The double-speed motor is used, speeds of the motor are 1400/2800r/min at 60HZ. Motor power is 550W at low speeds and 750W at high speeds. SA switch is desinged to select high speeds or low speeds, as well as high or low speeds in the reverse dirction. QS button is designed to start and stop motor.

## List of Electrics

Code	Name	Specification	Qty	Remarks
QS	Manual starter	KJD11-10ZF/4 380V 10A	1	
SA	Speed-change switch	T-16EXF64D-6	1	
M	Double-speed Motor	2/4pole 750/550W 2800/1400r/min 50HZ 3360/1680r/min 60HZ	1	
XT	Terminal board	jx5-1005	1	
M1	Cool pump motor	90W 50HZ or 60HZ	1	
SA1	Cool pump switch	LW39A-16C03/2	1	
SA2	Limit switch	LXW5-11Z	1	







Figure 5 Installation Diagram For Electrics

Figure 6 Interconnection Diagram of Electrics



### 7. Lubrication

The precision pure spindle—grease No. 2 is used for gear—box and spindle lubrication. The grease should be replaced once a year. Add lubrication oil No. 30 to the spindle—box and the up and down handle of supporting block every shift. Reference Figure 7 for the location of lubrication.

### 8. Lifting and Installation

After the machine arrives, you had better do a cross—check against packing list. If anything is damage or not complete, you need note and demand.

All locking handles must be locked before lift. <As shown in figure 8>.

Depth calculation of base is maximum area which the working table turns 360° around the vertical column.

Figure 9 is minimum dimension, you can adjust its height according to your request.

When installing the machine, bury the footscrew in a cement foundation according to the position of base holes, after the cement has condensed completely, place the machine on the cement foundation, adjust it to the demand of Go item on the inspection certificate with horizontal meter, then screw the footscrew steadily and evenly.




Figure 7 Location of Lubrication







Figure 8 Location of Lifting



Model	A x B	
	mm	in
Z5025A	635 x 360	25 x 14 <sup>3</sup> / <sub>16</sub>
Z5025 - 1A 3A	360 x 265	14 <sup>3</sup> / <sub>16</sub> x 10 <sup>7</sup> / <sub>16</sub>

## 9. Operation. Test Run. Adjustment

Pay attention to the following before operation:

1. Read the operation manual entirely and carefully before installing and starting.
2. Users should obey the rules for application of this machine.
3. Users must obey the method of lubrication of this machine.
4. Give some clearance between the tail of taper—shank of twist drill and touching point of unloading device. The tail of non—standard taper shank and improper sleeve of taper tool should not be used.
5. Clean the rust—resisting paint carefully and add lubricant.

Then run the machine from low speed to high speed and check for proper operation.

6. When tapping, after the motor must be stopped, then the reversal direction start motor.

## List of the Parts of Operation

<As shown in Figure 10>

No	Name	No	Name
1	Lock screw	10	Feed handle of spindle
2	Up and down handle of supporting block	11	Lock handle of supporting block
3	Tool retracting handle	12	Lock screw
4	Up and down handle of head box	13	Lock handle of working—table
5	Speed chang handle	14	Converting switch of double speed motor
6	Speed change handle	15	Start and stop switch of motor
7	Scale	16	Working table
8	Depth setting nut	17	Supporting table
9	Lock handle of head—box	18	Lock screws and nuts

Before starting the motor, the converting switch 14 should be in proper location. <"IR" for

low speed, "2R" for high speed; in the reversal direction, "1L" for low speed, "2L" for high -

speed >. Then push the switch 15 to "ON" for motor starting, push the switch to "OFF", the

motor stops. For reverse, push the switch 15 to "OFF" first, and point the switch 14 to "1L" or

"2L" position, and point the switch 14 to "1L" or "2L" position, then push switch 15 to "ON".

According to the speed plate, four <4 > different speeds of spindle can be obtained by chang-

ing handle 5 and 6. With switch 14, eight <8 > different speed can be obtained from 100 -

2900r/min. Pay attention to the following: before changing handles 5 and 6, the machine must

be stopped.

Up and down movement of headstock: loosening the lock handle 9, turning handle 4, the

spindle box can be moved upward and downward. And it can be rotated 0-360° around the col-

umn.

Spindle feed: turning handle 10 <clockwise >, the spindle goes downward, loosening handle

10 <clockwise >, the spindle goes upward, loosening handle 10, spindle automatically is reseted

under the spring force.

Tool stripping: pulling out tool releasing button 3 first and then pushing handle 10 upward.

the tools can be stripped. And pushing handle 3 in first, the tool can be installed again.

Hold the drilling depth: moving the depth setting nut 8 on the scale 7 to the required dimen-

tion.

Up and down movement of working table: loosening lock handle 11, turning handle 2, the

working table can be moved upward or downward. The supporting block can be rotated 0-360°

around the column by turning working table. The working table can be rotated 0-360° after re-

leasing handle 13.

Adjustment of spindle clearance: Gear box id mounted on the upper part of spindle box By re-

moving three connecting screws, taking off the gear box, loosening lock washer 2 <as show in

figure 11 >, the clearance of spindle can be adjusted by nut 1. Be care: if the clearance is too

small, overheating of the spindle bearing or other troubles may be happened.


Adjustment of resetting spring of spindle: by removing switch board 3, loosening lock screw 1, turning spring base 2, the springforce can be adjusted. Then tighten up screw 1 <as show in Figure 12>.

Adjustment of spindle box and locking device of the supporting block of working table: by tightening up the hex nut on screw 18, and twisting acorn nut on the hex nut, adjust the hex nuts <as shown in Figure 10> until the swinging angle of lock handles 9 and 11 are in right place, the tighten up the acorn nuts.

By removeing gear box as mentioned above, the motor maintenance can be done. Before pulling out stator for maintenance, the two lock screws on the right side of spindle box have to be unscrewed.

All parts of this machine have been adjusted before it is delivered, do not adjust unless it is necessary.

Figure 10






Figure 11




Figure 12

10. They are listed below

No	Name	Specification	Quantity
1	3-jaw drill chuck	1-13mm	1
2	Taper sleeve	3/2	1
3	Taper sleeve	3/1	1
4	Drill chuck holder	ZF01	1
5	wedge for taper shank tool	ZF02	1

11. Safety cover equipment

The safety cover equipment is available as requirement.

The organic glass cover can protect the operator effectively. It can move up

and down for covering different work—pieces.

13. Noise intensity

RPM	100	2900
dB	73	78



## 13. Part list &lt;as shown in figure 13—18&gt;.

No. Name	No. Name
1. bottom base	36. washer
2. spring washer	37. scaled ruler
3. hex nut	38. knurled nut
4. hose connector	39. round head screw
5. cover plate	40. round nut
6. round head screw	41. anti—motion washer
7. vertical column	42. bearing 80205E
8. flexible metal pipe	43. guide key
9. lift gear rack	44. spindle sleeve
10. vertical column top cover	45. feed gear rack
11. inner hex screw	46. spindle
12. eye screw	47. spindle box
13. cross slot screw	48. handle
14. inner hex screw	49. sleeve fasten ring
15. carth plate	50. bearing D2007107
16. cross slot screw	51. bearing cover
17. handle	52. o shape seal
18. handle	53. oil cup
19. flexible metal pipe	54. taper head fasten screw
20. hose connector	55. fixture sleeve
21. change switch	56. key
22. spring washer	57. worm gear Z28
23. toothed washer	58. sleeve
24. round head screw	59. small shaft
25. electromaganetic switch	60. gear Z17
26. tapered head fasten screw	61. connection rod
27. round head screw	62. handle base
28. worm shaft	63. handle ball
29. taper pin	64. handle bar
30. bush	65. handle base
31. bearing 8102	66. pin
32. hex nut	67. elastic block ring
33. taper head fasten screw	68. washer
34. round pin	69. spindle box
35. spring	70. fasten bolt.

OPERATION MANUAL

No. Name	No. Name
105. round head screw	105. round head screw
104. motor base	104. motor base
103. motor connect shaft	103. motor connect shaft
102. gear Z16	102. gear Z16
101. cover	101. cover
100. gear Z68	100. gear Z68
99. gear Z16	99. gear Z16
98. key	98. key
97. sleeve	97. sleeve
96. key	96. key
95. gear Z42	95. gear Z42
94. bearing 80203	94. bearing 80203
93. taper pin	93. taper pin
92. round head screw	92. round head screw
91. gear box	91. gear box
90. gear box	90. gear box
89. handle sleeve	89. handle sleeve
88. handle rod	88. handle rod
87. spring sleeve	87. spring sleeve
86. ruler base	86. ruler base
85. round head screw	85. round head screw
84. spring	84. spring
83. round head fasten screw	83. round head fasten screw
82. electric panel	82. electric panel
81. lift gear shaft Z16	81. lift gear shaft Z16
80. spring base	80. spring base
79. cover plate	79. cover plate
78. coil spring	78. coil spring
77. sink screw	77. sink screw
76. sink screw	76. sink screw
75. cover plate	75. cover plate
74. round head screw	74. round head screw
73. cover nut	73. cover nut
72. hex nut	72. hex nut
71. round head fasten screw	71. round head fasten screw
No. Name	No. Name
106. key	106. key
107. sleeve	107. sleeve
108. gear Z34	108. gear Z34
109. sleeve	109. sleeve
110. round head screw	110. round head screw
111. middle shaft	111. middle shaft
112. cover plate	112. cover plate
113. motor	113. motor
114. key	114. key
115. rivet	115. rivet
116. center shaft	116. center shaft
117. sleeve	117. sleeve
118. connect sheet	118. connect sheet
119. gear Z33	119. gear Z33
120. inner gear sheet	120. inner gear sheet
121. connector	121. connector
122. key	122. key
123. gear Z51	123. gear Z51
124. sleeve	124. sleeve
125. bearing 3056203	125. bearing 3056203
126. gear Z42	126. gear Z42
127. fixture ring	127. fixture ring
128. taper pin	128. taper pin
129. pin	129. pin
130. arm	130. arm
131. shaft pin	131. shaft pin
132. tape pin	132. tape pin
133. handle	133. handle
134. spring	134. spring
135. steel ball	135. steel ball

No. Name

136. small shaft

137. gear—worm gear

138. worm shaft

139. bearing 8102

140. sleeve

141. work table

No. Name

142. handle rod

143. ball

144. press block

145. turning shaft

146. bracket

147. sliding box

148. gear rack

Figure 13





Figure 14






Fig. 15






Fig. 16



Z5025A ✓

Z5025 -1A  
-3A

UPRIGHT DRILLING MACHINE

# INSPECTION CERTIFICATE

MAX. DRILLING DIAMETER

25mm (1 in)

SERIAL NO: Z103930

# INSPECTION CERTIFICATE

Page 1 of 4

This machine has been inspected and is

qualified for delivery according to

GB/T 4018.1~4018.2-1997. (eqv ISO 2773-1~2773-2:1973)

Director of Inspection Department:



President:



Date: 08. ) . 31






NOTEKEEPING FOR PRECISION TEST  
I. GEOMETRICAL PRECISION INSPECTION

NO	ITEMS	SKETCH	ACCURACY
----	-------	--------	----------

a	Machine level adjustment a) in the plane of cross direction		b
0.02	0.03/300 (0.0012"/12")		0.02

G1	Flatness of table surface and bottom base working surface	 	At length of 300(12") measured 0.03(0.0012") (flat or concave) 0.02
----	--	--	--

# INSPECTION CERTIFICATE

NO	ITEMS	SKETCH	ACCURACY	
			Permissible tolerances(mm)	Measured
G2	End face runout of work table		D= 300(12") 0.05 (0.002")	0.02
G3	Radial runout of axis of spindle taper hole a) At the place near the end face of spindle b) At the distance 200mm length from end face of spindle		L= 200(8") a) 0.020 (0.0008") b) 0.035 (0.0014")	a: 0.02  b: 0.02
G4	Perpendicular alignment of circular axis of spindle to the worktable and the bottom base working surface a) in the plane of cross direction b) in the plane of longitudinal direction		a) 0.06/300 * (0.0024"/12") ( $\alpha \leq 90^\circ$ ) b) 0.06/300 * (0.0024"/12")	a: 0.02  b: 0.02

Note: \* Is the distance between probes of indicator

INSPECTION CERTIFICATE

NO	ITEMS	SKETCH	Permissible	Measured
			tolerances (mm)	

G5	Perpendicular alignment of spindle sleeve to the table face (a) in the plane of cross direction (b) in the plane of longitudinal direction		a) 0.10/300 (0.004/12) ( $\alpha \leq 90^\circ$ ) b) 0.10/300 (0.004/12)	a: 0.04 b: 0.03
----	--	--	--	--------------------

P1	Change of perpendicular alignment of spindle axis to table face under the action of axial force		2/1000 * (0.08/40)	1.6
----	---	--	-----------------------	-----

II. WORKING PRECISION INSPECTION

Note: \* Is the distance between probes of indicator

# PACKING LIST

	Z5025A	Z5025 - 1A	Z5025 - 3A
serial No.			
case dimensions (L×W×H) cm	194 × 68 × 106	180 × 51 × 88	180 × 51 × 88
gross weight:kg	507	299	310
net weight:kg	404	243	254

No.	DESCRIPTION	SPECIFICATION	QTY	REMARKS
1	upright - drilling machine		1	
2	3 - jaw drill chuck	1 - 13mm	1	
3	drill chuck holder	ZF01	1	
4	wedge for taper shank tool	ZF02	1	
5	taper sleeve	3/1	1	
6	taper sleeve	3/2	1	
7	operation manual		1	
8	inspection certificate		1	
9	packing list		1	

packing inspector

date